



# High Performance, Low Power, ISM Band FSK/GFSK/OOK/MSK/GMSK Transceiver IC

Silicon Anomaly

**ADF7023-J**

This anomaly sheet describes the known bugs, anomalies, and workarounds for the [ADF7023-J](#) transceiver and relates to Silicon Revision 2.2, which has corresponding silicon revision readback codes of 0x70, 0x23, 0x02, and 0x02. See the [ADF7023-J](#) data sheet for details on how to read the silicon revision codes.

Analog Devices, Inc., is committed, through future silicon revisions, to continuously improve silicon functionality. Analog Devices tries to ensure that these future silicon revisions remain compatible with your present software/systems by implementing the recommended workarounds outlined here.

## ADF7023-J FUNCTIONALITY ISSUES

Silicon Revision Readback	Chip Marking	Silicon Status	Anomaly Sheet	No. of Reported Anomalies
Product Code MSB = 0x70 Product Code LSB = 0x23 Silicon Revision Code MSB = 0x02 Silicon Revision Code LSB = 0x02	ADF7023-JBCPZ	Release	Rev. A	3

### Rev. A

Information furnished by Analog Devices is believed to be accurate and reliable. However, no responsibility is assumed by Analog Devices for its use, nor for any infringements of patents or other rights of third parties that may result from its use. Specifications subject to change without notice. No license is granted by implication or otherwise under any patent or patent rights of Analog Devices. Trademarks and registered trademarks are the property of their respective owners.

One Technology Way, P.O. Box 9106, Norwood, MA 02062-9106, U.S.A.  
Tel: 781.329.4700 [www.analog.com](http://www.analog.com)  
Fax: 781.461.3113 ©2011–2012 Analog Devices, Inc. All rights reserved.

## FUNCTIONALITY ISSUES

Table 1. Receiver Sensitivity at 910 MHz [er005]

<b>Background Issue</b>	The 910 MHz channel falls exactly on the 35 <sup>th</sup> harmonic of the 26 MHz crystal reference. When the <a href="#">ADF7023-J</a> receiver is configured for reception at 910 MHz $\pm$ (IF bandwidth $\times$ 2), the receiver sensitivity can be degraded by up to 10 dB.
<b>Workaround</b>	The degradation in receiver sensitivity at 910 MHz $\pm$ (IF bandwidth $\times$ 2) can be further improved by using the following configuration: <ol style="list-style-type: none"> <li>1. Disable the AGC by setting AGC_LOCK_MODE (in Register RADIO_CFG_7, Address 0x113) = 0x01.</li> <li>2. Set the receiver gain to the maximum by setting AGC_MODE (Address 0x35D) = 0x36.</li> <li>3. Disable the ADC by writing 0x0F to MCR Register POWERDOWN_RX (Address 0x324).</li> </ol>
<b>Related Issues</b>	None.

Table 2. Receiver Sensitivity at 923 MHz[er006]

<b>Background Issue</b>	The 923 MHz channel falls exactly on the 71 <sup>st</sup> harmonic of 13 MHz. When the <a href="#">ADF7023-J</a> receiver is configured for reception at 923 MHz $\pm$ (IF bandwidth $\times$ 2), the receiver sensitivity can be degraded by up to 5 dB.
<b>Workaround</b>	The degradation in receiver sensitivity at 910 MHz $\pm$ (IF bandwidth $\times$ 2) can be minimized by using the separate match configuration.
<b>Related Issues</b>	None.

Table 3. Crystal Oscillator Low Frequency Spurs [er007]

<b>Background Issue</b>	Under certain conditions, low frequency spurs can be induced in the crystal oscillator of the <a href="#">ADF7023-J</a> . The crystal oscillator circuit of the <a href="#">ADF7023-J</a> can exhibit spurs under certain conditions. These spurs are evident at RF at an offset frequency of approximately 7 kHz to 8 kHz. The spurs are more likely to occur with <ul style="list-style-type: none"> <li>• Reduced C<sub>LOAD</sub></li> <li>• Reduced Temperature</li> <li>• Increased XOSC_CAP_DAC value</li> </ul>
<b>Workaround</b>	These spurs do not occur in the condition where the crystal input XOSC26N is driven by an external source. See the <a href="#">ADF7023-J</a> data sheet for details on configuring for crystal oscillator operation. Introducing a series 150 $\Omega$ resistor on Pin 13 XOSC26P (R <sub>5</sub> in Figure 1), together with limiting the XOSC_CAP_DAC setting to a maximum value of 4, will eliminate these spurs over the temperature range of the device.
<b>Related Issues</b>	None.




Figure 1. Recommended Crystal Oscillator Configuration

081834-001

**SECTION 1. ADF7023-J FUNCTIONALITY ISSUES**

Reference Number	Description	Status
er001	RC oscillator accuracy	Fixed
er002	External PA and LNA enable on ADCIN_ATB3 and ATB4	Fixed
er003	External PA and LNA enable on XOSC32KP_GP5_ATB1 and XOSC32KN_ATB2	Fixed
er004	Optimum uncalibrated image attenuation	Feature: Refer to <a href="#">ADF7023-J</a> data sheet (Rev. A or later)
er005	Receiver sensitivity at 910 MHz	Improved
er006	Receiver sensitivity at 923 MHz	Open
er007	Crystal oscillator low frequency spurs	Open

**NOTES**