



Robust, Industrial, Low Latency and Low Power 10 Mbps, 100 Mbps, and 1 Gbps Ethernet PHY

Silicon Anomaly

ADIN1300

This anomaly list describes the known bugs, anomalies, and workarounds for the [ADIN1300](#) Revision U1 silicon. The items listed apply to all packaged material that is branded as follows:

First Line [ADIN1300](#) (device identifier)
Second Line CCBZ or BCBZ
Third Line #1842 onward (Pb-free, date code, year, and week)
Fourth Line Nine-digit lot ID (assembly lot code)

Analog Devices, Inc., is committed, through future silicon revisions, to continuously improve silicon functionality. Analog Devices tries to ensure that these future silicon revisions remain compatible with your present software/systems by implementing the recommended workarounds outlined here.

ADIN1300 FUNCTIONALITY ISSUES

Silicon Revision Identifier	Silicon Status	Anomaly Sheet	Number of Reported Anomalies
Revision identifier is 0 and can be read from the PHY_ID_2 register, REV_NUM bit field	Released	Rev. 0	3

Rev. 0

[Document Feedback](#)

Information furnished by Analog Devices is believed to be accurate and reliable. However, no responsibility is assumed by Analog Devices for its use, nor for any infringements of patents or other rights of third parties that may result from its use. Specifications subject to change without notice. No license is granted by implication or otherwise under any patent or patent rights of Analog Devices. Trademarks and registered trademarks are the property of their respective owners.

One Technology Way, P.O. Box 9106, Norwood, MA 02062-9106, U.S.A.
Tel: 781.329.4700 ©2019 Analog Devices, Inc. All rights reserved.
[Technical Support](#) www.analog.com

FUNCTIONALITY ISSUES

Table 1. PHY Linking—1000BASE-T Master/Slave [er001]

Background	In the 1000BASE-T IEEE® standard, when both sides of a link are configured as master or slave preference, there is a small probability of the devices not establishing a link or taking longer to establish a link. Both sides being configured identically is considered a master/slave misconfiguration. It is therefore recommended that one side of the link be configured with the master preference and the other with the slave preference for any IEEE standard 1000BASE-T compliant physical layer (PHY) device.
Issue	The ADIN1300 PHY devices may experience issues linking at 1000BASE-T at a higher probability than expected if two ADIN1300 devices at either end of the link have identical hardware configuration settings of master or slave preference, have matching PHY addresses, and the PHY devices are powered up or released from a hardware reset at the same time (within 60 ms). The behavior arises from a synchronization issue between the PHY devices when they are powered up or released from a hardware reset at the same time, where they cannot resolve master/slave identities. This issue subsequently results in a master/slave resolution error, and linking cannot be established.
Workaround	There are multiple ways of avoiding this behavior as follows. Any one of the following options is sufficient to mitigate risk of nonlinking: <ul style="list-style-type: none"> • Configure the PHYs with different master/slave preferences by hardware pin configuration. • Configure the PHYs with different PHY addresses by hardware pin configuration. • Power the PHYs and release them from hardware reset >60 ms apart. • Use software to change the master/slave preference or issue a reset to the PHY. For users testing the EVAL-ADIN1300FMCZ evaluation boards, the boards are shipped in pairs. One of the boards comes with the LINK_ST/PHY_CFG1 pin configured for slave (MODE_1) and the other for master (MODE_2).
Related Issues	PHY linking—automatic MDIX.

Table 2. PHY Linking—Automatic MDIX [er002]

Background	The ADIN1300 PHY devices may experience longer link times or issues linking, when two ADIN1300 devices at either end of the link have identical hardware configuration settings of automatic media dependent interface crossover (auto MDIX), have matching PHY addresses, and the PHY devices are powered up or released from a hardware reset at the same time (within 60 ms).
Issue	The behavior arises from a synchronization issue between the PHY devices, when they are powered up or released from a hardware reset at the same time. This issue results in the autocrossover sequence being synchronized between both devices and changing at approximately the same time. Where no crossover cable is present between the PHYs, both PHYs use the same wire pair to transmit and same wire pair to receive, thereby not seeing the transmissions of the other to resolve the media dependent interface (MDI) until they drift apart.
Workaround	There are multiple interim ways of avoiding this behavior. Any one of the following options is sufficient to mitigate risk of longer link times or nonlinking for this version of silicon: <ul style="list-style-type: none"> • Configure the PHYs with different PHY addresses by hardware pin configuration. • Configure the PHYs with different automatic MDIX/MDI settings by hardware pin configuration. • Configure the PHYs with different master/slave settings by hardware pin configuration. • Power the PHYs and release them from hardware reset >60 ms apart. • Use software to change the MDIX/MDI setting or issue a reset to the PHY.
Related Issues	PHY linking—1000BASE-T master/slave.

Table 3. INT_N/CRS Pin Operation During Reset [er003]

Background	The INT_N/CRS pin is not deasserted during I/O pin configuration (while RESET_N is low). This behavior is observed as the INT_N/CRS pin is being driven low while RESET_N is low and is observed for all media access control (MAC) interface configurations.
Issue	The output enable on this pin is not being deasserted during I/O pin configuration.
Workaround	None.
Related Issues	None.

SECTION 1. ADIN1300 FUNCTIONALITY ISSUES

Reference Number	Description	Status
er001	Longer link times or issues linking when two ADIN1300 devices have same master/slave configuration	Open
er002	Longer link times or issues linking when two ADIN1300 devices at either end of the link have identical automatic MDIX hardware configuration settings.	Open
er003	INT_N/CRS state while RESET_N is low.	Open