



Precision Analog Microcontroller, 12-Bit Analog I/O, ARM7TDMI MCU

Silicon Anomaly

ADuC7122

This anomaly list describes the known bugs, anomalies, and workarounds for the [ADuC7122](#) MicroConverter® Revision C silicon.

First Line [ADuC7122](#)

Third Line C5I (revision identifier)

Analog Devices, Inc., is committed, through future silicon revisions, to continuously improve silicon functionality. Analog Devices tries to ensure that these future silicon revisions remain compatible with your present software/systems by implementing the recommended workarounds outlined here.

ADuC7122 FUNCTIONALITY ISSUES

Silicon Revision Identifier	Chip Marking	Silicon Status	Anomaly Sheet	No. of Reported Anomalies
All revisions of silicon	All silicon branded C5I	Released	Rev. A	5

Rev. A

[Document Feedback](#)

Information furnished by Analog Devices is believed to be accurate and reliable. However, no responsibility is assumed by Analog Devices for its use, nor for any infringements of patents or other rights of third parties that may result from its use. Specifications subject to change without notice. No license is granted by implication or otherwise under any patent or patent rights of Analog Devices. Trademarks and registered trademarks are the property of their respective owners.

One Technology Way, P.O. Box 9106, Norwood, MA 02062-9106, U.S.A.
Tel: 781.329.4700 ©2010-2014 Analog Devices, Inc. All rights reserved.
[Technical Support](#) www.analog.com

FUNCTIONALITY ISSUES

Table 1. External IRQ When Configured as Level Sensitive [er001]

Background	There are four external interrupt sources on the ADuC7122 that can be configured as edge triggered (rising or falling) or level triggered (active high or active low).
Issue	When any of the external interrupt sources are configured as level triggered, either active high or active low, the external pin must remain at the active level until the program vectors to the interrupt vector handler for that external interrupt. If the external pin is activated and triggers an interrupt that subsequently goes to an inactive level before the program vectors to the interrupt handler, the IRQSTA bit for the external interrupt may not be set. This results in the interrupt handler not knowing what interrupt source caused the part to vector to the interrupt vector.
Workaround	Edge-triggered interrupts don't have this problem. This issue is noted and will be addressed in any future revision of the silicon.
Related Issues	None.

Table 2. Disabling I²C Interface in Slave Mode When a Transfer Is in Progress [er002]

Background	Bit 0 of the I2CxSCTL register enables/disables the I ² C slave interface. Bit 6 of the I2CxSSTA register indicates whether the I ² C slave interface is busy.
Issue	If I ² C slave mode is enabled (Register I2CxSCTL, Bit 0 = 1) and a transfer is in progress with the master, then Bit 0 of the I2CxSCTL register should not be cleared to 0 to disable the I ² C slave interface until Bit 6 (the I ² C busy bit) of the I2CxSSTA register is cleared. When Bit 0 of the I2CxSCTL register is cleared to 0 and the busy bit is still set, the ADuC7122 can drive the SDAx pin low indefinitely. When this condition occurs, the ADuC7122 does not release the SDA pin unless a hardware reset condition occurs.
Workaround	When disabling I ² C slave mode by writing to Bit 0 of the I2CxSCTL register, first set Bit 0 of the I2CxMCTL register to 1 to enable master mode. Then, disable the slave mode by clearing Bit 0 of the I2CxSCTL register. Finally, clear Bit 0 of the I2CxMCTL register.
Related Issues	None.

Table 3. Operation of SPI in Slave Mode [er003]

Background	When in SPI slave mode, the ADuC7122 expects the number of clock pulses from the master to be divisible by 8 when the chip select pin is active.
Issue	The internal bit-shift counter does not reset when the chip select pin is deasserted. If the number of clocks from the master is not divisible by 8 when the chip select is active, incorrect data may be received or transmitted by the ADuC7122 because the bit-shift counter will not be at 0 for later transfers. The internal bit-shift counter for the transmit or receive buffers can only be reset by a hardware, software, or watchdog reset condition.
Workaround	Always ensure that the number of SPI clocks is divisible by 8 when the ADuC7122 chip select is active.
Related Issues	None.

Table 4. I²C Slave not Releasing the Bus [er004]

Background	When an I ² C read request happens, if the Tx FIFO of the slave is empty, the slave must NACK the request from the master. Then it must release the bus, allowing the master to generate a STOP condition.
Issue	If the Tx FIFO of the slave is loaded with a byte with an MSB of 0, just on the rising edge of SCL for the ACK/NACK, the slave will pull the SDA low and hold the line until the device is reset.
Workaround	Make sure the Tx FIFO is always loaded on time by preloading the Tx FIFO in the preceding Rx interrupt.
Related Issues	None.

Table 5. I²C Clock Stretch Issue [er005]

Background	Clock stretching is a feature that allows a device to halt the I ² C bus temporarily by holding SCL low. The I2CxSCON register Bit 6 enables clock stretching in slave mode. The I2CxMCON register Bit 3 enables clock stretching in master mode.
Issue	Writing to I2CxSCON Bit 6 or to I2CxMCON Bit 3 on the rising edge of SCL can cause a glitch that can be interpreted by other devices as a real clock edge and can hang the bus.
Workaround	Do not enable clock stretching.
Related Issues	None.

SECTION 1. ADuC7122 FUNCTIONALITY ISSUES

Reference Number	Description	Status
er001	External IRQ level triggered issue	Open
er002	Disabling I ² C interface in slave mode when a transfer is in progress	Open
er003	Operation of SPI in slave mode	Open
er004	I ² C slave not releasing the Bus	Open
er005	I ² C clock stretch issue	Open

I²C refers to a communications protocol originally developed by Philips Semiconductors (now NXP Semiconductors).