



SHARC+ Single Core High Performance DSP (Up to 1 GHz)

Silicon Anomaly List

ADSP-21560/21561/21564/21568

ABOUT ADSP-21560/21561/21564/21568 SILICON ANOMALIES

These anomalies represent the currently known differences between revisions of the SHARC+® ADSP-21560/21561/21564/21568 product(s) and the functionality specified in the ADSP-21560/21561/21564/21568 data sheet(s) and the Hardware Reference book(s).

SILICON REVISIONS

A silicon revision number with the form "-x.x" is branded on all parts. The REVID bits <31:28> of the TAPC0_IDCODE register can be used to differentiate the revisions as shown below.

Silicon REVISION	TAPC0_IDCODE.REVID
0.1	b#0001
0.0	b#0000

APPLICABILITY

Peripheral- and core-specific anomalies may not apply to all processors. See the table below for details. An "x" indicates that anomalies related to this peripheral/core apply only to the model indicated, and the list of specific anomalies for that peripheral/core appear in the rightmost column.

ANOMALY LIST REVISION HISTORY

The following revision history lists the anomaly list revisions and major changes for each anomaly list revision.

Date	Anomaly List Revision	Data Sheet Revision	Additions and Changes
03/11/2025	B	PrD	Added Anomalies 20000131 , 20000132 , 20000133
05/16/2023	A	PrA	Initial Version

SHARC+ and SHARC are registered trademarks of Analog Devices, Inc.

NR004940B

[Document Feedback](#)

Information furnished by Analog Devices is believed to be accurate and reliable. However, no responsibility is assumed by Analog Devices for its use, nor for any infringements of patents or other rights of third parties that may result from its use. Specifications subject to change without notice. No license is granted by implication or otherwise under any patent or patent rights of Analog Devices. Trademarks and registered trademarks are the property of their respective owners.

One Analog Way, Wilmington, MA 01887 U.S.A.
©2025 Analog Devices, Inc. All rights reserved.
[Technical Support](#) www.analog.com

SUMMARY OF SILICON ANOMALIES

The following table provides a summary of ADSP-21560/21561/21564/21568 anomalies and the applicable silicon revision(s) for each anomaly.

No.	ID	Description	Rev 0.0	Rev 0.1
1	20000002	Data Forwarding from Rn/Sn to DAG Register May Fail in Presence of Stalls	x	x
2	20000003	Transactions on SPU and SMPU MMR Regions May Cause Errors	x	x
3	20000031	GP Timer Generates First Interrupt/Trigger One Edge Late in EXTCLK Mode	x	x
4	20000062	Writes to the SPI_SLVSEL Register Do Not Take Effect	x	x
5	20000069	PCSTK and MODE1STK Loads Do Not Occur If Next Instruction Is L2 or L3 Access	x	x
6	20000072	Floating-Point Computes Targeting F0 Register Can Cause Pipeline Stalls	x	x
7	20000096	Type 18a USTAT Instructions Fail When Following Specific Code Sequence	x	x
8	20000097	SMPU11 Does Not Block Write Accesses From Core or DMA Requester	x	x
9	20000103	Unreliable SPDIF Receiver Clock Output Pulse Width at Sample Rates Above 96KHz	x	x
10	20000128	IRPTL Writes Erroneously Clear Pending FIRx/IIRx Accelerator Interrupts	x	x
11	20000131	xSPI Boot OTP Initialization Requires Byte Masking for Writes	x	x
12	20000132	Invalid Device Number Programmed in OTP Error Code May Be Misreported by Boot ROM	x	x
13	20000133	Boot ROM May Encounter Error When CRC Protection Is Enabled with Page Mode Enabled	x	x

Key: x = anomaly exists in revision
 . = Not applicable

DETAILED LIST OF SILICON ANOMALIES

The following list details all known silicon anomalies for the ADSP-21560/21561/21564/21568 including a description, workaround, and identification of applicable silicon revisions.

1. 20000002 - Data Forwarding from Rn/Sn to DAG Register May Fail in Presence of Stalls:

DESCRIPTION:

An instruction involving a DAG operation such as address generation or modify following a type5a instruction may fail under the following conditions:

1. The type5a instruction updates the source register of the subsequent DAG operation.
2. The type5a instruction uses the same source register to both load to the DAG register and store the result of the compute operation.
3. The DAG operation follows within six instructions of the type5a instruction.
4. The pipeline is stalled due to a data/control dependency or an L1 memory bank conflict.

When these conditions are met, the type5a instruction produces the expected result and updates the DAG register correctly. However, the data forwarded to the DAG is incorrect. The DAG register that is used as the destination in the subsequent DAG operation is incorrectly updated.

Consider the following type5a instruction sequence:

```
1: r2 = r2 - r13, i4 = r2; // r2 is destination of compute AND source of DAG load
2: if eq jump target1;    // Dependency on previous instruction stalls the pipe
3: nop;
4: nop;
5: nop;
6: nop;
7: i5 = b2w (i4);         // Uses source register (i4) stored to by type5a instruction
```

In the above case, i5 (line 7) is updated with an incorrect value, even though i4 (line 1) contains the correct value. The same condition is true if the instruction on line 7 appears anywhere in lines 3 through 6.

WORKAROUND:

There are two potential workarounds for this issue:

1. Split the type5a instruction which conforms to the use case into two separate instructions.
2. Avoid using the relevant DAG register in a DAG operation within six instructions of the type5a instruction.

This workaround may be built into the development tool chain and/or into the operating system source code. For tool chains and operating systems supported by Analog Devices, consult the "Silicon Anomaly Tools Support" help page in the applicable documentation and release notes for details.

For all other tool chains and operating systems, see the appropriate supporting documentation for details.

APPLIES TO REVISION(S):

0.0, 0.1

2. 20000003 - Transactions on SPU and SMPU MMR Regions May Cause Errors:

DESCRIPTION:

Non-secure reads or writes to the MMR space of the upper half of each SPU and SMPU instance are erroneously blocked and cause a bus error when configured as a non-secure completer.

For each instance of the SPU and SMPU, the affected MMR address range can be calculated as follows:

- Lower bound = Instance Address Offset + 0x800
- Upper bound = Instance Address Offset + 0xFFF

WORKAROUND:

Do not access the documented system MMR ranges from a non-secure completer.

APPLIES TO REVISION(S):

0.0, 0.1

3. 20000031 - GP Timer Generates First Interrupt/Trigger One Edge Late in EXTCLK Mode:**DESCRIPTION:**

When any GP Timer is configured in External Clock (EXTCLK) mode, the first interrupt/trigger should occur when the corresponding **TIMER_DATA_ILAT** bit sets after the **TIMER_TMRn_CNT** register reaches the value programmed in the **TIMER_TMRn_PER** register. Instead, the interrupt/trigger and the setting of the **TIMER_DATA_ILAT** bit events occur one signal edge later. At this point, the **TIMER_TMRn_CNT** register will have rolled over to 1. Subsequent interrupts/triggers occur after the correct number of edges.

For example, if **TIMER_TMRn_PER**=7, the first interrupt/trigger occurs after the timer pin samples eight edges. From that point forward, interrupts/triggers will correctly occur every seven signal edges.

WORKAROUND:

For interrupts/triggers to occur every **n** edges detected on the timer pin, the **TIMER_TMRn_PER** register must be configured to **n-1** for the initial event and then reprogrammed to **n** for subsequent events. Consider the following pseudocode:

```
TIMER_TMRn_PER = n-1;    // Configure PERIOD register with n-1
TIMER_RUN_SET = 1;       // Enable the timer
TIMER_TMRn_PER = n;      // Configure PERIOD register with n
```

The second write to the **TIMER_TMRn_PER** register does not take effect until the 2nd period; therefore, this sequence can be performed when the timer is first enabled.

APPLIES TO REVISION(S):

0.0, 0.1

4. 20000062 - Writes to the SPI_SLVSEL Register Do Not Take Effect:**DESCRIPTION:**

A single write to the **SPI_SLVSEL** register should change the state of the register and cause the modified software-controlled SPI target selects to assert or de-assert. Instead, a single write to **SPI_SLVSEL** has no effect.

WORKAROUND:

Any write to **SPI_SLVSEL** should be done twice (back-to-back) with the same value in order for the change to take effect.

APPLIES TO REVISION(S):

0.0, 0.1

5. 20000069 - PCSTK and MODE1STK Loads Do Not Occur If Next Instruction Is L2 or L3 Access:**DESCRIPTION:**

Writes to the **PCSTK** and **MODE1STK** registers may not happen correctly if the next instruction is an access to a non-L1 memory location, as in the following code sequence:

```
1: MODE1STK = r0;
2: PCSTK    = dm(0,i6); // i6 points to L2 or L3 memory space
3: px2      = dm(0,i6);
```

Because **i6** points to non-L1 memory in this sequence, the **MODE1STK** write on line 1 fails due to the use of **i6** on line 2. The write to **PCSTK** on line 2 also fails because of the same use of **i6** on line 3.

WORKAROUND:

Insert a **NOP** instruction between the write to the **PCSTK/MODE1STK** register and the next memory access instruction.

This workaround can be built into the development tool chain and/or into the operating system source code. For tool chains and operating systems supported by Analog Devices, consult the "Silicon Anomaly Tools Support" help page in the applicable documentation and release notes for details.

For all other tool chains and operating systems, see the appropriate supporting documentation for details.

APPLIES TO REVISION(S):

0.0, 0.1

6. 20000072 - Floating-Point Computes Targeting F0 Register Can Cause Pipeline Stalls:**DESCRIPTION:**

Any floating-point compute instruction with **F0** as the destination register causes pipeline stalls when followed immediately by a no-operand or single-operand compute instruction with **Rx** as the unused source register. Consider the following code sequence:

```
F0 = PASS F4;
R10 = PASS R11; // Y operand is not used. Flushed to 0 in opcode by assembler.
```

WORKAROUND:

There are two possible workarounds:

1. Do not use the F0 register as the destination in the above code sequence.
2. Ensure that the instruction that immediately follows the compute operation is not of the form described in the code example above.

APPLIES TO REVISION(S):

0.0, 0.1

7. 20000096 - Type 18a USTAT Instructions Fail When Following Specific Code Sequence:**DESCRIPTION:**

Type 18a ISA/VISA register bit manipulation instructions (**BIT SET**, **BIT CLR**, **BIT TGL**, **BIT TST**, and **BIT XOR**) that use either USTAT register can fail when immediately following an external memory (**EXT_MEM**) or system MMR (**SMMR**) read-write sequence and a read of a core memory-mapped register (**CMMR**) involving the same USTAT register. Consider the following pseudo-code sequence:

```
1: USTAT# = dm(EXT_MEM|SMMR); // EXT_MEM or SMMR read to USTAT1 or USTAT2
2: dm(EXT_MEM|SMMR) = USTAT#; // EXT_MEM or SMMR write from the same USTAT register
3: USTAT# = dm(CMMR); // CMMR read to the same USTAT register
4: bit <op> USTAT# <data32>; // <op> = SET|CLR|TGL|TST|XOR, using the same USTAT register
```

In this code sequence, the type 18a instruction in line 4 erroneously performs the bit operation on the value loaded to the USTAT register in instruction 1 rather than performing the operation on the expected value loaded in instruction 3.

WORKAROUND:

Insert a **NOP** instruction before the type 18a instruction in the above code sequence to avoid the issue.

APPLIES TO REVISION(S):

0.0, 0.1

8. 20000097 - SMPU11 Does Not Block Write Accesses From Core or DMA Requester:**DESCRIPTION:**

The system memory protection unit covering the SPI flash address memory space (**SMPU11**) is not fully functional for write accesses. It properly detects a write protection violation when a core or DMA requester performs a write access to that space, but it does not block the write access itself as expected.

WORKAROUND:

Use write protection in the OSPI0 controller to block the writes to the flash memory address space, as described in this pseudo-code:

```
OSPI_WRPROT_UP = Upper Flash Memory Address; // Set upper memory boundary
OSPI_WRPROT_LWR = Lower Flash Memory Address; // Set lower memory boundary
OSPI_WRPROT_CTL = 0x2; // Enable write protection
```

After write protection for the memory region is enabled, write protect the OSPI0 registers using the SPU. This step ensures that the configuration is not unintentionally changed during run-time.

APPLIES TO REVISION(S):

0.0, 0.1

9. 20000103 - Unreliable SPDIF Receiver Clock Output Pulse Width at Sample Rates Above 96KHz:**DESCRIPTION:**

When the sampling rate of the SPDIF receiver input stream (FS_Rate) is above 96 KHz, the positive pulse width of the SPDIF receiver TDM output clock (SPDIF_RX_TDMCLK_O) can be as low as the period of the SPDIF receiver module clock. The negative pulse width can be as high as one SPDIF receiver module clock period less than the ideal clock period. As a result, audio peripherals such as the ASRC, SPORT, and DAI pins may not function properly when SPDIF_RX_TDMCLK_O is used as the clock source.

WORKAROUND:

Do not use the SPDIF_RX_TDMCLK_O output clock as the source for external peripherals when the FS rate is above 96 KHz.

The Precision Clock Generator (PCG) can be used to divide the clock down such that audio peripherals like the ASRC, SPORT, and DAI pins may function internally; however, the clock and frame sync outputs from the PCG will still exhibit the duty cycle problem and must not be used to interface with external components.

APPLIES TO REVISION(S):

0.0, 0.1

10. 20000128 - IRPTL Writes Erroneously Clear Pending FIRx/IIRx Accelerator Interrupts:**DESCRIPTION:**

Any IRPTL register write instruction (e.g., **BIT SET**, **BIT CLR**, or **BIT TGL**), regardless of the value of the argument, clears any pending FIRx/IIRx accelerator channel completion interrupt latched in the **IRPTL** register when executed. This can result in an FIRx/IIRx channel completion interrupt miss.

WORKAROUND:

1. Do not use the **BIT SET**, **BIT CLR**, or **BIT TGL** **IRPTL** write instructions to generate or ignore interrupts when FIRx/IIRx accelerators are used.
2. Use the System Event Controller (SEC) to manage the FIRx/IIRx accelerator channel completion interrupts when **IRPTL** must be explicitly written to manage other interrupts.

APPLIES TO REVISION(S):

0.0, 0.1

11. 20000131 - xSPI Boot OTP Initialization Requires Byte Masking for Writes:**DESCRIPTION:**

xSPI RAM initialization that is supported during preboot through OTP always enables byte masking in the xSPI controller. There is no way to disable it through OTP. This limits the RAM devices to those which support byte masking.

WORKAROUND:

RAM devices which do not support byte masking must be initialized through initialization code rather than through OTP.

APPLIES TO REVISION(S):

0.0, 0.1

12. 20000132 - Invalid Device Number Programmed in OTP Error Code May Be Misreported by Boot ROM:**DESCRIPTION:**

If the user programs an invalid device number in OTP memory, the boot ROM may encounter an exception in the cleanup routine. The error is due to an access to invalid MMR space for the non-existing device instance. As a result, the error code reported by the boot ROM indicates an error due to a core exception. It may not directly indicate an error due to an invalid device number.

WORKAROUND:

None

APPLIES TO REVISION(S):

0.0, 0.1

13. 20000133 - Boot ROM May Encounter Error When CRC Protection Is Enabled with Page Mode Enabled:**DESCRIPTION:**

If CRC protection of the payload is enabled with page mode enabled, the Boot ROM may encounter an error and jump to the error handler, resulting in a boot failure.

WORKAROUND:

If CRC protection of the payload is needed, page mode must be disabled. If page mode is enabled by default, it can be disabled by programming `dBBootCmd` in OTP or through a second-stage boot.

APPLIES TO REVISION(S):

0.0, 0.1