

# Product/Process Change Notice - PCN 24 0027 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887, USA

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title: Datasheet Update of Electrical Test Requirements for Legacy Space LTC (RH Products)

Publication Date: 07-May-2024

Effectivity Date: 07-May-2024 (the earliest date that a customer could expect to receive changed material)

**Revision Description:** Initial Release

### **Description Of Change:**

Update Table 2: Electrical Test Requirements

- 1. Change from MIL-STD-883 to MIL-PRF-38535 Test Requirements.
- Remove Group B and add Group C, D, and E end-point electrical parameters.

### **Reason For Change:**

To standardize and align the RH QCI process and requirement to Legacy Aerospace.

### Impact of the change (positive or negative) on fit, form, function & reliability:

There is no change to the form, fit, function, quality, or reliability of the device.

Product Identification (this section will describe how to identify the changed material)

Date codes later than 2306.

## **Summary of Supporting Information:**

Qualification is not required. Changes will be reflected on the new product data sheet revision F.

#### **Supporting Documents**

Attachment 1: Type: Datasheet Specification Comparison

ADI PCN 24 0027 Rev - RH119 Datasheet Comparison .pdf...

Note: If applicable, the device material declaration will be updated due to material change.

### **ADI Contact Information:**

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: Europe: Japan: Korea: Rest of Asia:

PCN\_Americas@analog.com PCN\_Europe@analog.com PCN\_Japan@analog.com PCN\_Korea@analog.com PCN\_ROA@analog.com

# **Appendix A - Affected ADI Models:**

# Added Parts On This Revision - Product Family / Model Number (37)

RH1009/RH1009MH RH1013M/RH1013MW RH1021-5/RH1021CMH-5 RH1056A/RH1056AMW RH108A/RH108AW RH129/RH129AH RH27C/RH27AEW RH6105/RH6105MW RH1009 / RH1009MW RH1014M / RH1014MW RH1021-5 / RH1021CMW-5 RH1078M / RH1078MH RH1128M / RH1128MW RH137 / RH137H RH27C / RH27CW RH6200M / RH6200MW

RH1011/RH1011H RH1016M/RH1016MW RH1034-1.2/RH1034MH-1.2 RH1078M/RH1078MW RH117/RH117H RH1498M/RH1498MW RH27C/RH27EW RH1011 / RH1011W RH101A / RH101AW RH1034-1.2 / RH1034MW-1.2 RH1086M / RH1086MH RH118 / RH118W RH1499M / RH1499MW RH37C / RH37CH

RH1013M / RH1013MH RH1021-5 / RH1021BMH-5 RH1056A / RH1056AMH RH108A / RH108AH RH119 / RH119W RH1814M / RH1814MW RH37C / RH37CW

| Appendix B - Revision History: |              |                         |                 |
|--------------------------------|--------------|-------------------------|-----------------|
| Rev                            | Publish Date | <b>Effectivity Date</b> | Rev Description |
| Rev                            | 07-May-2024  | 07-May-2024             | Initial Release |