

Gerber Setup

General Layers Drill Drawing Apertures Advanced			
Layers To Plot			
Extension	Layer Name	Plot	Mirror
-GTO	Silkscreen Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GTP	Paste Mask Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GTS	Solder Mask Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GTL	L1 TOP	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-G1	L2 GND	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-G2	L3 PWR	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GBL	L4 BOT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GBS	Solder Mask Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GBP	Paste Mask Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GBO	Silkscreen Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GM1	Assembly Drawing Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GM18	MECH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GKO	Keep-Out Layer	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GPT	Top Pad Master	<input checked="" type="checkbox"/>	<input type="checkbox"/>
-GPB	Bottom Pad Master	<input checked="" type="checkbox"/>	<input type="checkbox"/>