



2.0 Physical differences

Tray 50-9816




TOP VIEW




BOTTOM VIEW

Tray 50-8000 (Top view different but bottom view is similar)



TOP VIEW




BOTTOM VIEW

The tray 50-9816 and 50-8000 stackable with each other.


Both trays have silk screen printing indicating the tray part number, 8000 for 50-8000 and 9816 for 50-9816.



Tray 50-9816 solder ball at the perimeter corner of the unit will have high chance to knock into the tray wall during transportation when the units is rotated and tilted.



Tray 50-8000 solder ball at the perimeter of the unit will not hit any tray wall during transportation when the unit is rotated and tilted.



3.0 Affected devices for BGA (Y)

LTM4681