



## Product/Process Change Notice - PCN 26\_0126 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887, USA

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. An acceptance or concern response should be submitted to ADI promptly. Any requests for samples of changed material or additional information must be made within 30 days of the notification. In accordance with JEDEC Standard 046, customers should acknowledge receipt of the PCN within 30 days of the PCN delivery. ADI contact information is listed below. Note: Revised fields are indicated by a red field name. See Appendix B for revision history.

**Lack of acknowledgment of the PCN within 30 days constitutes acceptance of the change. After the acknowledgment, a lack of additional requests within 90 days constitutes acceptance of the change.**

<b>PCN Title:</b>	Assembly Site Transfer of Select MQFP Products to Carsem Malaysia
<b>Publication Date:</b>	19-May-2026
<b>Effectivity Date:</b>	21-Aug-2026 <i>(the earliest date that a customer could expect to receive changed material)</i>
<b>Revision Description:</b>	Initial Release.

### Description Of Change:

Assembly site of MQFP is moving from Amkor Philippines AP1 to Carsem Malaysia (CRS).

### Reason For Change:

MQFP will be transferred to Carsem Malaysia (CRS), a qualified assembly site due to package discontinuance at Amkor Philippines AP1.

### Impact of the change (positive or negative) on fit, form, function & reliability:

There is no change on form, fit, function and reliability.

### Summary of Supporting Information:

Qualification has been performed per Industry Standard Test Methods. See attached Qualification Results.

### Supporting Documents:

**Attachment 1: Type:** Qualification Results Summary

ADI\_PCN\_26\_0126\_Rev\_-\_MQFP at CRS Reliability Results.pdf

Note: If applicable, the device material declaration will be updated due to material change.

### ADI Contact Information:

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

<b>Americas:</b>	<b>Europe:</b>	<b>Japan:</b>	<b>Korea:</b>	<b>Rest of Asia:</b>
PCN_Americas@analog.com	PCN_Europe@analog.com	PCN_Japan@analog.com	PCN_Korea@analog.com	PCN_ROA@analog.com

## Appendix A - Affected ADI Models:

### Added Parts On This Revision - Product Family / Model Number (14)

AD7722 / AD7722ASZ	AD7859 / AD7859ASZ	AD7859 / AD7859ASZ-REEL	AD7859 / AD7859BSZ	AD7859 / AD7859LASZ
AD7859 / AD7859LASZ-REEL	AD9240 / AD9240ASZ	AD9240 / AD9240ASZRL	AD9260 / AD9260ASZ	AD9260 / AD9260ASZRL
ADUC832 / ADUC832BSZ	ADUC832 / ADUC832BSZ-REEL	ADUC841 / ADUC841BSZ62-3	ADUC841 / ADUC841BSZ62-5	

**Appendix B - Revision History:**

<b>Rev</b>	<b>Publish Date</b>	<b>Effectivity Date</b>	<b>Rev Description</b>
Rev. -	19-May-2026	21-Aug-2026	Initial Release.