



TOP ASSEMBLY

NOTES: UNLESS OTHERWISE SPECIFIED.

1. WORKMANSHIP SHALL BE IN ACCORDANCE WITH IPC-A-610.
2. MASK THE SOLDER STENCIL WHERE SMT PARTS ARE OMITTED.
3. DEPANELIZE BOARDS AFTER ASSEMBLY AND ROUTE-OUT THE BREAKOUT TABS ON FOUR SIDES OF THE BOARD EDGE.
4. DO NOT APPLY ANY KIND OF ASSEMBLY STAMP OR QA STAMP TO ANY BOARD.
5. MARK APPROPRIATE IC AND VERSION.

- 2. MASK THE SOLDER STENCIL WHERE SMT PARTS ARE OMITTED.**

- ### 3. DEPANELIZE BOARDS AFTER ASSEMBLY AND ROUTE-OUT THE BREAKOUT TABS ON FOUR SIDES OF THE BOARD EDGE

- 4. DO NOT APPLY ANY KIND OF ASSEMBLY STAMP OR QA STAMP TO ANY BOARD.**

- 5 MARK APPROPRIATE IC AND VERSION:

VERSION	MODULE
-A	LTM4620
-B	LTM4620A
-C	LTM4628
-D	LTM4630
-E	LTM4630-1
-F	LTM4630A
-G	LTM4631