



ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



Maxim Integrated


SC1905-DB2400 ASSEMBLY DRAWING

(REVA)

SILK TOP

ASSY TOP


ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION




Maxim Integrated

SC1905-DB2400 ASSEMBLY DRAWING

(REVA)

ASSY TOP


ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION


CAUTION



Maxim Integrated
SC1905–DB2400 ASSEMBLY DRAWING
(REVA)

ASSY TOP


ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



Maxim Integrated

SC1905-DB2400 ASSEMBLY DRAWING

(REVA)

ASSY TOP