

PCN # 09_0041 Qual Plan

| TEST | CONDITIONS | SAMPLE SIZE | RESULTS |
|--|---------------------------------|-------------|--|
| Autoclave* | JEDEC-STD-22-Method A102 | 3x82 | Pass |
| Autoclave* | JEDEC-STD-22-Method A102 | 3x82 | Pass |
| Autoclave* | JEDEC-STD-22-Method A102 | 3x82 | Pass |
| Highly Accelerated Stress Test (HAST)* | JEDEC-STD-22-Method A110 | 3x82 | Pass |
| Highly Accelerated Stress Test (HAST)* | JEDEC-STD-22-Method A110 | 3x82 | Pass |
| Highly Accelerated Stress Test (HAST)* | JEDEC-STD-22-Method A110 | 3x82 | Pass |
| High Temperature Operating Life* | JEDEC JESD22-A108 | 3x82 | In-process. Expected completion 04/2009 |
| High Temperature Operating Life* | JEDEC JESD22-A108 | 3x82 | In-process. Expected completion 04/2009 |
| High Temperature Operating Life* | JEDEC JESD22-A108 | 3x82 | In-process. Expected completion 04/2009 |

*Preconditioned Per JEDEC/IPC J-STD-020