



Product/Process Change Notice - PCN 11_0183 Rev. B

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

Note: Revised fields are indicated by a red field name. See Appendix B for revision history.

PCN Title: ADF7023 Metal Mask Revision

Publication Date: 07-Mar-2012

Effectivity Date: 07-Mar-2012 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Advise of additional functional changes

Description Of Change

The metal mask of ADF7023 product has been revised from silicon revision 1.2 to 1.3.

(Note: 1.3 is an internal ADI reference number)

Rev B: Additional functional changes have been made as described in attached document "ADF7023 Silicon Rev. 2.2 PCN Technical Content"

Reason For Change

To address all issues in published anomaly list (attached).

Impact of the change (positive or negative) on fit, form, function & reliability

This change has no impact on fit, form or reliability of the ADF7023 product.

The published anomaly list is no longer applicable to the new revision and the device and will operate as per the existing datasheet with the exception of the items listed in the attached document (ADF7023 Silicon Rev. 2.2 PCN Technical Content). It is important to review this document to determine if control firmware needs to be modified to ensure full backward compatibility.

A datasheet update (RevC) will be made to include the listed functionality changes and to document new optional functionality.

Product Identification *(this section will describe how to identify the changed material)*

All devices on or after date code 1129 will use the new silicon revision.

The device can be identified by reading back firmware revision number 2.2 from the internal ROM location. See datasheet for details.

Summary of Supporting Information

A combination of simulation and ATE Testing has been completed to support this change.

Supporting Documents

Attachment 1: Type: Detailed Change Description

ADI_PCN_11_0183_Rev_B_ADF7023_Anomaly_0_Final.doc

Attachment 2: Type: Detailed Change Description

ADI_PCN_11_0183_Rev_B_PCN technical content list ADF7023 rev0.1.pdf

For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Existing Parts - Product Family / Model Number (2)

ADF7023 / ADF7023BCPZ	ADF7023 / ADF7023BCPZ-RL			
-----------------------	--------------------------	--	--	--

Appendix B - Revision History

Rev	Publish Date	Rev Description
Rev. -	22-Sep-2011	Initial Release
Rev. A	11-Jan-2012	Update to advise date code effectivity
Rev. B	07-Mar-2012	Advise of additional functional changes

Analog Devices, Inc.

DocId:1852 Parent DocId:None Layout Rev:6