



Product/Process Change Notice - PCN 14_0186 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title: AD9554 datasheet correction

Publication Date: 27-Aug-2014

Effectivity Date: 27-Aug-2014 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

The contents of table 21 (Mx Pin External EEPROM Function at Startup) table is being corrected

Reason For Change

Initial datasheet release incorrectly identified pin M1 as SDA and pin M2 as SCL, when in fact it is the opposite.

Impact of the change (positive or negative) on fit, form, function & reliability

none

Product Identification *(this section will describe how to identify the changed material)*

not applicable

Summary of Supporting Information

No change was made to the device, so no re-qualification is needed. Datasheet correction only.

Supporting Documents None

For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models				
Added Parts On This Revision - Product Family / Model Number (3)				
AD9554 / AD9554BCPZ	AD9554 / AD9554BCPZ-REEL	AD9554 / AD9554BCPZ-REEL7		

Appendix B - Revision History			
Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	27-Aug-2014	27-Aug-2014	Initial Release