



Product/Process Change Notice - PCN 14_0263 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title: ADA4177-2 Data Sheet Change

Publication Date: 04-Dec-2014

Effectivity Date: 04-Mar-2015 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

Change TC沃斯 limit for MSOP package from 1.0uV/C to 1.6uV/C.

Reason For Change

Identifying MSOP TC沃斯 limit from SOIC.

Impact of the change (positive or negative) on fit, form, function & reliability

No negative impact to fit or reliability.

Product Identification *(this section will describe how to identify the changed material)*

No Marking changes.

Summary of Supporting Information

This change will be reflected in Rev B of the ADA4177-2 data sheet.

Supporting Documents None

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Added Parts On This Revision - Product Family / Model Number (3)

ADA4177-2 / ADA4177-2ARMZ

ADA4177-2 / ADA4177-2ARMZ-R7

ADA4177-2 / ADA4177-2ARMZ-RL

Appendix B - Revision History

| Rev | Publish Date | Effectivity Date | Rev Description |
|------------|---------------------|-------------------------|------------------------|
| Rev. - | 04-Dec-2014 | 04-Mar-2015 | Initial Release |
| | | | |

Analog Devices, Inc.

DocId:3135 Parent DocId:None Layout Rev:7