



DS5001FP 128k Soft Microprocessor Chip

www.maxim-ic.com

REVISION C6 ERRATA

The errata listed below describe situations where DS5001FP revision C6 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to fix these errata in subsequent die revisions.

This errata sheet only applies to DS5001FP revision C6 components. Revision C6 components are branded on the topside of the package with a six-digit code of the form yywwC6, where yy and ww are two-digit numbers representing the year and work-week of manufacture, respectively. To obtain an errata sheet on another DS5001FP die revision, visit the website at www.maxim-ic.com.

There are no errata on this device.