

ERRATA SHEET

MAX32590

Revision B4 Errata

The errata listed below describe situations where MAX32590 revision B4 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc. may, at its own discretion, take future steps to correct these errata when the opportunity to redesign the product presents itself. Prior to that, Maxim has determined the following potential workarounds that customers may want to consider when addressing one of the situations described below.

This errata sheet only applies to MAX32590 revision B4 components. Revision B4 components are branded on the topside of the package with a six-digit code in the form yywwB4, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another MAX32590 die revision, go to www.maximintegrated.com/MAX32590.

This errata sheet requires an NDA for distribution. Contact the Business Unit for availability at www.maximintegrated.com/MAX32590.