

The World Leader in High Performance Signal Processing Solutions



*i*Sensor®

ADIS1633x/PCB – Prototyping Tips




Mark Looney
*i*Sensor Applications Engineer
February 2011



iSensor® The Simple Solution for Sensor Integration

ADIS1633x/PCBZ Documentation

ADIS16334/PCBZ Mounting & Connection Diagram




- NOTES**
1. USE FOUR M2 MACHINE SCREWS TO ATTACH THE ADIS16334BMLZ.
 2. USE FOUR M3 MACHINE SCREWS TO ATTACH THE INTERFACE PCB.


J1/J2 Pin Assignments

	J1		
RST	1	2	SCLK
CS	3	4	DOUT
DNC	5	6	DIN
GND	7	8	GND
GND	9	10	VCC
VCC	11	12	VCC

	J2		
DNC	1	2	GND
DNC	3	4	DIO3
GND	5	6	DIO4
DNC	7	8	DNC
DNC	9	10	DNC
DIO2	11	12	DIO1



J1/J2 Ribbon Cable Interface Parts



Ribbon Cable
3M P/N 3625/12 (100m)

Ribbon Crimp Connector
3M P/N 152212-0100-GB



◆ **Contacts:**

● **Applications Engineer:**

Mark Looney
mark.looney@analog.com
1-336-605-4139

● **Marketing:**

Bob Scannell
bob.scannell@analog.com
1-336-605-4031

More Information on *i*Sensor Evaluation Tools:

● **www.analog.com/isensor-evaluation**