



Product/Process Change Notice - PCN 24_0056 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887, USA

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title:	PM155S and PM156S SMD Datasheet Update
Publication Date:	25-Apr-2024
Effectivity Date:	28-Jul-2024 <i>(the earliest date that a customer could expect to receive changed material)</i>
Revision Description:	Initial Release

Description Of Change:

Please be advised that Analog Devices has made a change to the PM155S and PM156S product datasheet to facilitate improvement in manufacturing capability. The changes are shown on the attached pages.

Table I. Electrical performance characteristics.

1. Input Bias Current- changed from +/-3nA to +/-5nA

Reason For Change:

To facilitate improvement in manufacturing capability.

Impact of the change (positive or negative) on fit, form, function & reliability:

This datasheet change does not impact the fit, form, function, or reliability of the PM155S/PM156S.

Product Identification *(this section will describe how to identify the changed material)*

Date Codes starting from 2347.

Summary of Supporting Information:

Changes have been reflected on the new product datasheet Rev F.

Supporting Documents

Attachment 1: Type: Datasheet Specification Comparison

[ADI_PCN_24_0056_Rev_-PM155S and PM156S Datasheet Specification Compar...](#)

Note: If applicable, the device material declaration will be updated due to material change.

ADI Contact Information:

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas:	Europe:	Japan:	Korea:	Rest of Asia:
PCN_Americas@analog.com	PCN_Europe@analog.com	PCN_Japan@analog.com	PCN_Korea@analog.com	PCN_ROA@analog.com

Appendix A - Affected ADI Models:

Added Parts On This Revision - Product Family / Model Number (3)

PM155S / 5962R9863601VGA

PM155S / 5962R9863601VPA

PM156S / 5962R9863602VGA

Appendix B - Revision History:

Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	25-Apr-2024	28-Jul-2024	Initial Release