



## Product Discontinuance Notice - PDN 18\_0060 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

### PDN Title:

Discontinuance of HMC products due to loss of manufacturing and supply capability.

**Publication Date:** 05-Oct-2018

**Last Time Buy Date:** 15-Mar-2019

**Last Time Ship Date:** 15-Mar-2020

### Revision Description:

Initial Release

### Reason For Discontinuance

Loss of manufacturing and supply capability.

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

**Americas:** PDN\_Americas@analog.com

**Europe:** PDN\_Europe@analog.com

**Japan:** PDN\_Japan@analog.com

**Rest of Asia:** PDN\_ROA@analog.com

### PDN 18\_0060 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
126674-HMC847LC5	HMC847	126578-HMC854LC5	No	
126674-HMC848LC5	HMC848	126578-HMC855LC5	No	
128921-HMC843LC4B	HMC843	118777-HMC722LC3C	No	
128921-HMC844LC4B	HMC844	125614-HMC851LC3C	No	
129126-HMC841LC4B	HMC841	125614-HMC853LC3	No	
129151-HMC842LC4B	HMC842	125614-HMC850LC3	No	
HMC1027BG	HMC1027	ADN4612ACPZ	No	
HMC1027BGTR	HMC1027	ADN4612ACPZ	No	
HMC1068	HMC1068G	none	n/a	
HMC1068-SX	HMC1068G	none	n/a	
HMC1069	HMC1069G	none	n/a	
HMC1069-SX	HMC1069G	none	n/a	
HMC6545LP5E	HMC6545	none	n/a	
HMC6545LP5ETR	HMC6545	none	n/a	
HMC6590	HMC6590G	none	n/a	
HMC6590-SX	HMC6590G	none	n/a	
HMC7282B	HMC7282BG	none	n/a	

HMC7545ABLP47E	HMC7545	none	n/a	
HMC7545ABLP47ETR	HMC7545	none	n/a	
HMC7590	HMC7590G	none	n/a	
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
HMC7590-SX	HMC7590G	none	n/a	
HMC841LC4B	HMC841	HMC853LC3	No	
HMC841LC4BTR	HMC841	HMC853LC3TR	No	
HMC841LC4BTR-R5	HMC841	HMC853LC3TR-R5	No	
HMC842LC4B	HMC842	HMC850LC3	No	
HMC842LC4BTR	HMC842	HMC850LC3TR	No	
HMC842LC4BTR-R5	HMC842	HMC850LC3TR-R5	No	
HMC843LC4B	HMC843	HMC722LC3C	No	
HMC843LC4BTR	HMC843	HMC722LC3CTR	No	
HMC843LC4BTR-R5	HMC843	HMC722LC3CTR-R5	No	
HMC844LC4B	HMC844	HMC851LC3C	No	
HMC844LC4BTR	HMC844	HMC851LC3CTR	No	
HMC844LC4BTR-R5	HMC844	HMC851LC3CTR-R5	No	
HMC847LC5	HMC847	HMC854LC5	No	
HMC847LC5TR	HMC847	HMC854LC5TR	No	
HMC847LC5TR-R5	HMC847	HMC854LC5TR-R5	No	
HMC848LC5	HMC848	HMC855LC5	No	
HMC848LC5TR	HMC848	HMC855LC5TR	No	
HMC848LC5TR-R5	HMC848	HMC855LC5TR-R5	No	

**Appendix A - PDN 18\_0060 Revision History**

Rev	Publish Date	Rev Description
Rev. -	05-Oct-2018	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1295 Layout Rev:2 Parent DocId:None