



# Product Discontinuance Notice - PDN 18\_0085 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

**PDN Title:**

Obsolescence of Material Number HMC737LP4E and HMC737LP4ETR

**Publication Date:** 12-Dec-2018

**Last Time Buy Date:** 12-Dec-2019

**Last Time Ship Date:** 12-Dec-2020

**Revision Description:**

Initial Release

**Reason For Discontinuance**

Discontinued due to decreased customer demand.

**Comments**

Recommended replacement: ADF5610 58 MHz - 15 GHz integrated PLLVCO.

There are a number of similar discrete products that can also be used to replace this product. See [www.analog.com/vco](http://www.analog.com/vco)

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

<b>Americas:</b> PDN_Americas@analog.com	<b>Europe:</b> PDN_Europe@analog.com	<b>Japan:</b> PDN_Japan@analog.com
		<b>Rest of Asia:</b> PDN_ROA@analog.com

### PDN 18\_0085 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
HMC737LP4E	HMC737	See Comments	N/A	ADF5610; similar discrete parts on <a href="http://www.analog.com/vco">www.analog.com/vco</a>
HMC737LP4ETR	HMC737	See Comments	N/A	ADF5610; similar discrete parts on <a href="http://www.analog.com/vco">www.analog.com/vco</a>

### Appendix A - PDN 18\_0085 Revision History

Rev	Publish Date	Rev Description
Rev. -	12-Dec-2018	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1332    Layout Rev:2    Parent DocId:None