



Product Discontinuance Notice - PDN 21_0100 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of AD9860 and AD9862 Broadband Communication Processors

Publication Date: 25-Jun-2021

Last Time Buy Date: 25-Jun-2022

Last Time Ship Date: 25-Jun-2023

Revision Description:

Initial Release

Reason For Discontinuance

The assembly manufacturing flow is being discontinued.

Comments

The unit process supporting this package type, TQFP, is discontinued at the assembly sub-contractor.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 21_0100 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD9860BSTZ	AD9860	AD9961BCPZ	no	could consider Radioverse products, like ADRV9002
AD9860BSTZRL	AD9860	AD9961BCPZRL	no	could consider Radioverse products, like ADRV9002
AD9862BSTZ	AD9862	AD9963BCPZ	no	could consider Radioverse products, like ADRV9002
AD9862BSTZRL	AD9862	AD9963BCPZRL	no	could consider Radioverse products, like ADRV9002

Appendix A - PDN 21_0100 Revision History

Rev	Publish Date	Rev Description
Rev. -	25-Jun-2021	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1694 Layout Rev:3 Parent DocId:None