



Product Discontinuance Notice - PDN 12_0004 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Obsolescence of ADV7520NK

Publication Date: 23-Jan-2012

Last Time Buy Date: 23-Jan-2013

Last Time Ship Date: 23-Jan-2014

Reason For Discontinuance

All models of the ADV7520NK are being obsoleted due to decreased customer demand.
Not recommended for new designs.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

| | | |
|--|--------------------------------------|---|
| Americas: PDN_Americas@analog.com | Europe: PDN_Europe@analog.com | Japan: PDN_Japan@analog.com |
| | | Rest of Asia: PDN_ROA@analog.com |

PDN 12_0004 Discontinued Parts Material List

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|--------------------|----------------|-------------------|-----------------------|-----------------------------|
| ADV7520NKBBCZ-80 | ADV7520NK | ADV7523ABCZ-1RL | No | The ADV7513 for new designs |
| ADV7520NKBBCZRL-80 | ADV7520NK | ADV7523ABCZ-P-1RL | No | The ADV7513 for new designs |

Appendix A - PDN 12_0004 Revision History

| Rev | Publish Date | Rev Description |
|--------|--------------|-----------------|
| Rev. - | 23-Jan-2012 | Initial Release |

Analog Devices, Inc. Proprietary Information

DocId:430 Layout Rev:2 Parent DocId:None