



DS26324

3.3V, 16-Channel, E1/T1/J1 Short-Haul Line Interface Unit

www.maxim-ic.com

REVISION A2 ERRATA

The errata listed below describe situations where DS26324 revision A2 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS26324 revision A2 components. Revision A2 components are branded on the top side of the package with a six-digit code in the form yywwA2, where yy and ww are two-digit numbers representing the year and work-week of manufacture, respectively. To obtain an errata sheet on another DS26324 die revision, visit our website at www.maxim-ic.com/errata.

There are no known errata for this revision at this time.